

Republic of the Marshall Islands

MARITIME ADMINISTRATOR

11495 COMMERCE PARK DRIVE, RESTON, VIRGINIA 20191-1506

TELEPHONE: +1-703-620-4880 FAX: +1-703-476-8522

EMAIL: INVESTIGATIONS@register-iri.com WEBSITE: www.register-iri.com

MARINE SAFETY ADVISORY No. 03-23

To: Owners/Operators, Masters, Nautical Inspectors, Recognized Organizations

Subject: RESCUE BOAT LIFTING ARRANGEMENT FAILURE

Date: 22 February 2023 (renewed for 2025)

The Republic of the Marshall Islands (RMI) Maritime Administrator (the “Administrator”) has recently been notified of a marine casualty which occurred aboard an RMI-registered ship that resulted in the injury of two crewmembers.

During a planned drill, the ship’s rescue boat was being lowered to the water with two crewmembers aboard when the release hook support post failed. The rescue boat and two crewmembers fell about 9 meters to the water. The two crewmembers were quickly recovered from the water and transported ashore for medical treatment. Immediately prior to the incident, the rescue boat had been hoisted, swung over the side, and lowered several meters without anyone on board.

During the investigation, it was found that significant deterioration of the lower end of the support post for the release hook had occurred due to corrosion (see Figure 1). The lower side of the release hook support post was below the deck and only visible following removal of a portable fuel tank.



Figure 1: Photo of the rescue boat release hook support structure taken after the incident, showing significant deterioration of the post.

This MSA is evaluated annually by the Administrator and expires one year after its issuance or renewal unless otherwise noted, superseded, or revoked.

The Jiangyin Wolong model “JY40KR” rescue boat involved in this incident was manufactured in 2008. No defects or issues were noted when the boat was tested in 2019 or in November 2022 during the last annual inspection.

The Administrator recommends that owners, operators, and Masters of RMI-registered vessels fitted with Jiangyin Wolong “JY40KR” rescue boats thoroughly inspect the release hook and entire support post, including mounting hardware, for signs of deterioration.

Additionally, the Administrator recommends that owners, operators, and Masters ensure monthly inspections of life-saving appliances include thorough inspections of lifting arrangements for all onboard lifeboats and rescue boats with specific emphasis on hidden or hard to access components.