

# Republic of the Marshall Islands

## MARITIME ADMINISTRATOR

11495 COMMERCE PARK DRIVE, RESTON, VIRGINIA 20191-1506  
TELEPHONE: +1-703-620-4880 FAX: +1-703-476-8522  
EMAIL: maritime@register-iri.com WEBSITE: www.register-iri.com

### YACHT CODE SUPPLEMENT No. 01-22

**To: Yacht Owners/Captains, Managers, Agents, Recognized Classification Societies, and Appointed Representatives**

**Subject: SUPPLEMENT TO YACHT CODE AMENDING AND INSERTING CHAPTER II, SECTION(S) 15.2.4.5 THROUGH 15.2.4.8**

**Publication Date: 30 January 2021**

In accordance with Chapter I, Section §2.1.1.2 of the Republic of the Marshall Islands Yacht Code 2021 (the “Code”), this supplement inserts and amends Chapter II, section(s) 15.2.4.5 through 15.2.4.8 into the Code as follows:

- .5 Spare charges shall be provided on board for 100% of the first four portable fire extinguishers and at least 50% of each type and capacity of the remaining portable fire extinguishers capable of being recharged on board. Fire extinguishers installed in excess to the minimum requirements, may be regarded as spare charges / extinguishers and may be counted towards the required spare charge requirements.
- .6 Fire extinguishers that are regarded as spare, as referenced in §15.2.4.5 above, are to be indicated on the fire control plan with a note “Spare extinguisher”.
- .7 When the extinguishers cannot be recharged onboard, additional spare extinguishers shall be provided in the same quantities as required by §15.2.4.5 above.
- .8 In addition to the above, where spare fire extinguishers have been installed in accordance with §15.2.4.5 above, a minimum of two spare extinguishers of each type shall be kept in storage for replacement of any installed extinguisher which is found unserviceable or discharged.

This supplement shall be deemed to be incorporated into the Code and shall take full force and effect as of the Publication Date listed above.