

Republic of the Marshall Islands

MARITIME ADMINISTRATOR

11495 COMMERCE PARK DRIVE, RESTON, VIRGINIA 20191-1506
TELEPHONE: +1-703-620-4880 FAX: +1-703-476-8522
EMAIL: maritime@register-iri.com WEBSITE: www.register-iri.com

YACHT SAFETY ADVISORY No. 08-22

To: Yacht Owners/Captains, Managers, Agents, Recognized Class Societies and Appointed Representatives

Subject: UNAVAILABILITY OF NEW EMERGENCY POSITION INDICATING RADIO BEACONS

Date: 8 August 2022

The Republic of the Marshall Islands Maritime Administrator (the “Administrator”) has received reports of vessels encountering difficulties in procuring Emergency Position Indicating Radio Beacons (EPIRBs) that are compliant with the performance standards established in IMO Resolution [MSC.471\(101\)](#), *Performance Standards for Float-Free Emergency Position-Indicating Radio Beacons (EPIRBs) Operating on 406 MHz*.

This resolution recommends that float-free EPIRBs operating on the frequency 406 megahertz (MHz), which form part of the Global Maritime Distress and Safety System, conform to performance and type-approval standards not inferior to those as specified in the table below.

EPIRB Installation Date	Applicable IMO Standard(s)
On or after 1 July 2022 ¹	IMO Resolution MSC.471(101)
Before 1 July 2022	IMO Resolution A.810(19) , as amended by resolutions MSC.56(66) and MSC.120(74) , and type-approval standards not inferior to those specified in resolution A.696(17)

As the shortages of EPIRBs meeting the latest technical standards and delays in receiving them are expected to be temporary, the Administrator advises that:

- Existing IMO Resolution [A. 810\(19\)](#) compliant EPIRBs (those installed before 1 July 2022) may continue to be used by replacing the battery prior to its expiry date until such time as they can no longer be maintained and are retired.
- If an IMO Resolution [MSC.471\(101\)](#) compliant EPIRB is unavailable for installation after 1 July 2022, an IMO Resolution [A. 810\(19\)](#) compliant EPIRB may be installed and used until such time an IMO Resolution [MSC. 471\(101\)](#) compliant EPIRB becomes available. This substitution will be allowed through 31 December 2023 by the Administrator with written documentation showing the unavailability of the new EPIRB.
- Non-SOLAS vessels may install either IMO Resolution [A.810\(19\)](#) or IMO Resolution [MSC .471\(101\)](#) compliant EPIRBs.

¹ See IACS [UI SC 295](#) (July 2021) for an interpretation of the phrase “installed on or after 1 July 2022.”

This YSA is evaluated annually by the Administrator and expires one year after its issuance or renewal unless otherwise noted, superseded, or revoked.