

Republic of the Marshall Islands

MARITIME ADMINISTRATOR

11495 COMMERCE PARK DRIVE, RESTON, VIRGINIA 20191-1506
TELEPHONE: +1-703-620-4880 FAX: +1-703-476-8522
EMAIL: maritime@register-iri.com WEBSITE: www.register-iri.com

YACHT SAFETY ADVISORY No. 10-22

To: Yacht Owners/Captains, Managers, Agents, Recognized Class Societies and Appointed Representatives

Subject: SECOND GLOBAL POSITIONING SYSTEM ROLLOVER - 2022

Date: 6 September 2022

This Yacht Safety Advisory (YSA) supersedes YSA No. 04-22. It has been amended to extend the deadline for rectification from 31 August 2022 to 31 December 2022.

Further to YSA No. [01-22](#), a second Global Positioning System (GPS) Week Number Rollover event was scheduled for 15 May 2022. When the rollover occurred, the GPS units of some manufacturers displayed erroneous date information and communication functions did not work properly.

Navigation and communication equipment may be affected. Stand-alone GPS receivers and equipment using GPS chips could produce data that is 19.6 years in the past (29 September 2002), resulting in positioning instability and position errors (e.g., GPS position acquisition failure, etc.).

The positional fix can be restored by carrying out a cold start on some units. The cold start will not, however, resolve the incorrect date. To fix this issue, GPS manufacturers must carry out a software update. In some cases, the GPS unit may need to be replaced with a newer model.

The Republic of the Marshall Islands Maritime Administrator (the “Administrator”) requests that:

.1 Vessel owners and operators:

- contact their GPS manufacturers to determine if the equipment onboard their vessels will require a service technician to update the software; and
- rectify the GPS equipment issue at the first available opportunity, but no later than 31 December 2022.

.2 Vessel Masters:

- make appropriate entries in the Global Maritime Distress and Safety System and Deck Log Books; and

This YSA is evaluated annually by the Administrator and expires one year after its issuance or renewal unless otherwise noted, superseded, or revoked.

- keep boarding pilots and port State control advised if the discrepancy exists on their vessels.

The Administrator will issue dispensation letters, as necessary, for GPS units malfunctioning as the result of the rollover event. Please contact the Administrator at: radio@register-iri.com for a dispensation letter or additional information.