

MARITIME SAFETY COMMITTEE  
97th session  
Agenda item 22

MSC 97/22/Add.1/Corr.1  
2 May 2017  
Original: ENGLISH

**REPORT OF THE MARITIME SAFETY COMMITTEE ON ITS  
NINETY-SEVENTH SESSION**

**Corrigendum**

**ANNEX 5**

**RESOLUTION MSC.413(97)  
(adopted on 25 November 2016)**

**AMENDMENTS TO THE INTRODUCTION AND PART A OF THE INTERNATIONAL  
CODE ON INTACT STABILITY, 2008 (2008 IS CODE)**

1 In the existing paragraph 3 of the annex, the reference to "figure 1", set out in the new paragraph 2.31, is replaced with "figure 2.8-1".

**ANNEX 6**

**RESOLUTION MSC.414(97)  
(adopted on 25 November 2016)**

**AMENDMENTS TO THE INTRODUCTION AND PART A OF THE INTERNATIONAL  
CODE ON INTACT STABILITY, 2008 (2008 IS CODE)**

2 In the existing paragraph 3 of the annex, the reference to "figure 1", set out in the new paragraph 2.31, is replaced with "figure 2.8-1".


ANNEX 7

RESOLUTION MSC.415(97)  
(adopted on 25 November 2016)

AMENDMENTS TO PART B OF THE INTERNATIONAL  
CODE ON INTACT STABILITY, 2008 (2008 IS CODE)

3 In the annex, the existing figure 2.7-1 is replaced with the following:

"



**Figure 2.7.2 – Diagrams showing the intended meaning of parameters  $\alpha$ ,  $\beta$ ,  $x$ ,  $y$  and  $h$ .  $F_t$  shows the vector of the applied wire tension."**