

REPUBLIC OF THE MARSHALL ISLANDS

MARITIME ADMINISTRATOR

11495 COMMERCE PARK DRIVE RESTON, VIRGINIA 20191-1507

> TEL: +1-703-620-4880 FAX: +1-703-476-8522

> > 2023

Email: technical@register-iri.com

TECHNICAL CIRCULAR

| Circular Number: 12 | Revision: 1 | Page: 1 of 1 | Date: 6 September 2 |
|---------------------|-------------|--------------|---------------------|
|---------------------|-------------|--------------|---------------------|

Loss of Anchor

1.0 Introduction

To ensure a consistent response in loss of anchor cases, Republic of the Marshall Islands (RMI) Recognized Organizations (ROs) are instructed to follow these procedures when handling such cases on RMI-flagged vessels.

2.0 Procedure

- 2.1 On being notified of a loss of anchor, a Short Term Cargo Ship Safety Construction Certificate valid for a maximum of two months may be issued without specific authorization from the RMI Maritime Administrator (the "Administrator").
- 2.2 If a longer timeframe is required, the RO must request authorization from the Administrator per Marine Notice <u>2-011-4</u> with respect to a serious safety-related matter. The request must be sent to <u>technical@register-iri.com</u> and cover:
 - .1 any special operational or construction considerations;
 - .2 the shipowner's corrective action plan; and
 - .3 a recommendation on the term of validity for the certificate.
- 2.3 The following notations must be included on the Short-Term Cargo Ship Safety Construction Certificate when issued:
 - .1 Tug assistance is to be provided, at the discretion of the Master, while entering port, leaving port, and while navigating in confined waters; and
 - .2 Main Engine/propulsion is to be kept on "Stand By" at all times while at anchor.
